

From: SAN BRUNO ARCHIVE

Date Copied/Mailed: 2/21/03

HPS-4RA-265

Copier: POLYAK

Name

DOCUMENT

Achieve File ID: 181-60A 269 Box 9

Title: Acceptance of Bldg SOG; recommendation of

Serial No: 460

Pages: 3

Notes: NRDL turnover to shipyard

SAN FRANCISCO NAVAL SHIPYARD
SAN FRANCISCO 24, CALIFORNIA

758
A 3-140
3-240
3-210
ADDRESS REPLY:
COMMANDER
CODE NO.
460 REFER TO FILE

18 July 1955

MEMORANDUM

53145

From: Commander, San Francisco Naval Shipyard
To: Commanding Officer, U.S. Naval Radiological Defense Laboratory

Subj: Acceptance of Building 506

Ref: (a) Board to survey Shipyard Facilities being retruned by NRDL,
memo of 18 July 1955, Subj: Acceptance of Building 506;
recommendation of

1. Effective this date, Building 506 is accepted and returned to the custody of the Shipyard.
2. The existing condition and necessary alterations for return to Shipyard use are noted in reference (a).

W. L. TURNEY

Copy to:
Director, USNRDL
Code 140
Code 400
Code 800
Code 830 (832, 833)

"Our Service for Ships Means Ships for Service"

53145

SAN FRANCISCO NAVAL SHIPYARD
SAN FRANCISCO 24, CALIFORNIA

ADDRESS REPLY:
COMMANDER
CODE NO.
AND REFER TO FILE
460

18 July 1955

MEMORANDUM

From: Board to Survey Shipyard Facilities being returned by NRDL
To: Commanding Officer, U.S. Naval Radiological Defense Laboratory and
Commander, San Francisco Naval Shipyard

Subj: Acceptance of Building 506; recommendation of

Ref: (a) CO, USNRDL and ComSanFranNavShipyard memo of 24 March 1955

Encl: (1) Dir., USNRDL ltr 3-730-145 JEL:el of 18 July 1955

1. In accordance with reference (a), an inspection was made on 14 July of Building 506 to determine the acceptability for return to the Shipyard.
2. The building was determined to be in good order and free from all fire hazards.
3. As the building is not to be placed in use immediately, all utilities have been secured.
4. Condition of the building for security purposes was satisfactory. The keys were accepted from the representative of the NRDL. As the building is not to be placed into use immediately, the keys were turned over to the representative of the Security Division (Code 832).
5. The Shipyard has not established an immediate planned use of the building. Recommendations for major physical changes required to return the building to its original condition are therefore withheld pending announcement of future use.
6. The Director, U.S. Naval Radiological Defense Laboratory, has furnished a statement, enclosure (1), to the effect that this building is free from any harmful radiological contamination. However, enclosure (1) states the following recommendations:
 - a. A radiation monitor accompany working parties on the sewer systems for on the job monitoring until the present drain lines are replaced.
 - b. The drain lines which are removed from Building 506 in the future be disposed as low level radioactive waste so that they will not go to the salvage yard for possible re-use.
 - c. A radiation monitor accompany working parties on the duct work of hoods in Rooms 35 and 36.

"Our Service for Ships Means Ships for Service"

53145

7. It is recommended that Building 506 be accepted by the Shipyard.

M. G. JANSSEN, ENS, CEC, USNR
Chairman

M. J. CAPETANICH
Fire Chief

J. B. STEFANAC, CAPTAIN, USN
Member, Administrative Department

D. H. HEREL
Security Division

W. J. HART, LCDR, USN
Member, USNRDL

W. R. MIXON
Recorder